

Part 573 Safety Recall Report**14V-802****Manufacturer Name :** Ford Motor Company**Submission Date :** DEC 18,2014**NHTSA Recall No. :** 14V-802**Manufacturer Recall No. :** 14B09**Manufacturer Information :**

Manufacturer Name : Ford Motor Company

Address : 330 Town Center Drive

Suite 500 Dearborn MI 48126-2738

Company phone : 1-866-436-7332

Population :

Number of potentially involved : 462,911

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2005-2008 Ford Mustang

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : NR

Descriptive Information : Ford Motor Company (Ford) is conducting a recall for certain model year 2005 – 2008 Mustang vehicles equipped with driver airbags containing Takata PSDI-4 inflators.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Production Dates : AUG 01, 2004 - JUN 30, 2007

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

☐ Not sequential VINs

Vehicle : 2005-2006 Ford GT

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : NR

Descriptive Information : Ford Motor Company (Ford) is conducting a recall for certain model year 2005 – 2006 GT vehicles equipped with driver airbags containing Takata PSDI-4 inflators.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free

line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Production Dates : FEB 11, 2005 - JAN 30, 2006

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

☐ Not sequential VINs

Description of Defect :

Description of the Defect : NHTSA requested that Ford expand the current regional field service action on Ford Mustang and Ford GT vehicles equipped with Takata PSDI-4 inflators to the 50 States and Federalized Territories.

Description of the Safety Risk : The Takata driver front airbag inflators in the affected vehicles could rupture if the vehicle is involved in a crash where the supplemental front airbags are designed to deploy. If this occurs, it may increase the risk of injury to the vehicle occupants.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : TK Holdings

Address : 888 16th Street NW

Suite 800 Washington DISTRICT OF COLUMBIA 20006

Country : United States

Chronology :

June 19, 2014: At the Agency's request, Ford submitted a letter confirming its participation in a program to retrieve inflators from specified vehicle populations in Florida, Hawaii, Puerto Rico, and U.S. Virgin Islands [NHTSA Recall No. 14V-343, Ford No. 14B04]

November 10, 2014: Ford notified the Agency regarding a report of a ruptured driver airbag inflator on a 2007 model year Ford Mustang, equipped with a Takata PSDI-4 inflator, in North Carolina.

December 3, 2014: NHTSA requested that Ford expand the current regional field service action on Ford Mustang and Ford GT vehicles equipped with Takata PSDI-4 inflators to the 50 States and Federalized Territories.

December 16, 2014: Ford's Field Review Committee approved an expansion of 14V-343 to a 50 State and Federalized Territories to replace specific driver airbag inflators.

Description of Remedy :

Description of Remedy Program : Owners will be notified by mail and instructed to take their vehicle(s) to a Ford or Lincoln dealer to have the driver airbag inflator replaced. There will be no charge to owners for this service.

In accordance with Part 573.13(d)(1), Ford is excluding reimbursement for costs incurred by owners for repair of this concern because Ford's original warranty program would provide for a free repair for this concern for customers.

Ford will forward a copy of the notification letters to dealers to the Agency when available.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Notifications to Dealers will occur on December 18, 2014. Mailing of owner notification letters has not been determined.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported